

General Environmental Incident Summary

Incident: 4046 **Date/Time Notice:** 3/22/2016 1530 **DEM Incident No:**

Responsible Party: Oneok Rockies Midstream

Date Incident: 3/21/2016 **Time Incident:** 1700 **Duration:**

County: McKenzie **Twp:** 151 **Rng:** 98 **Sec:** 35 **Qtr:**

Lat: 47.85153 **Long:** -103.18160 **Method:** Interpolation from map

Location Description: Garden Creek Plant
3007 121st AVE NW
Watford City, ND 58854

Submitted By: Levi Weltikol

Affiliation:

Address: 2700 Lincoln Ave SE

City: Sidney

State: MT

Zip:

Received By:

Contact Person:

2700 Lincoln Ave SE
Sidney, MT

Distance Nearest Occupied Building:

Release Contained: Yes

Type of Incident: Hydraulic Hose Failure

Description of Released Contaminant: Hydraulic oil

Volume Spilled: 2.00 gallons

Ag Related: No

EPA Extremely Hazardous Substance: No

Reported to NRC: Unknown

Cause of Incident:

Hose on rental fork lift failed.

Risk Evaluation:

No immediate Risk

of Fatalities:

of Injuries:

Affected Medium: 03 - soil

Potential Environmental Impacts:

No Environmental Impacts

Action Taken or Planned:

Sprayed lightly on gravel on location. impacted gravel removed

Wastes Disposal Location:

Agencies Involved:

Updates

Date: 3/22/2016 **Status:** Reviewed - Follow-up Required

Author: Souder, Taylor

Updated Volume:

Notes:

Further follow-up needed.

Date: 4/20/2016 **Status:** Inspection

Author: O'Gorman, Brian

Updated Volume:

Notes:

Arrived on location at 9:10. 39 degrees F, foggy, calm winds. Spoke with the plant supervisor Gary Hastings. Mr. Hastings provided me with before and after photos of the release (added to folder). He explained to me that a hydraulic hose had broken and released onto the surface of the plant. The impacted gravel/soils were removed and replaced with clean soil/gravel. Recommend no further follow-up at this time.